








## EM(+) Series/ EM(-) Series

			
<ul style="list-style-type: none"> <li>EM-00 ※1</li> </ul>	<ul style="list-style-type: none"> <li>EM-0 ※1</li> </ul>	<ul style="list-style-type: none"> <li>EM-1 ※2</li> </ul>	<ul style="list-style-type: none"> <li>EM-2A ※2</li> </ul>
			
<ul style="list-style-type: none"> <li>EM-2B ※2</li> </ul>	<ul style="list-style-type: none"> <li>EM-2C ※1</li> </ul>	<ul style="list-style-type: none"> <li>EM-3 ※2</li> </ul>	

- ※1 storage boxes are for small gauge hexagonal carrying cases.
- ※2 storage boxes are for large gauge hexagonal carrying cases.

### Specifications

Set Range (mm)	Length (mm)	Tolerance	Roundness	Cylindricity
0.100mm ~ 0.975mm	40.00	(+2~+5) $\mu\text{m}$	1.3 $\mu\text{m}$	1.3 $\mu\text{m}$
1.000mm ~ 12.975mm	50.00	(+2~+5) $\mu\text{m}$	1.3 $\mu\text{m}$	1.3 $\mu\text{m}$
13.000mm ~ 19.000	50.00	(+1~+5) $\mu\text{m}$	1.6 $\mu\text{m}$	1.6 $\mu\text{m}$

- Sizes are indicated on the plastic cases for gauges up to 1.525mm and are laser engraved on gauges 1.525mm and larger along with the letter "P" for plus pins and the letter "M" for minus pins.

### Specifications

Set Range (mm)	Length (mm)	Tolerance	Roundness	Cylindricity
0.100mm ~ 0.975mm	40.00	(-2~-5) $\mu\text{m}$	1.3 $\mu\text{m}$	1.3 $\mu\text{m}$
1.000mm ~ 12.975mm	50.00	(-2~-5) $\mu\text{m}$	1.3 $\mu\text{m}$	1.3 $\mu\text{m}$
13.000mm ~ 19.000	50.00	(-1~-5) $\mu\text{m}$	1.6 $\mu\text{m}$	1.6 $\mu\text{m}$

- Sizes are indicated on the plastic cases for gauges up to 1.525mm and are laser engraved on gauges 1.525mm and larger along with the letter "P" for plus pins and the letter "M" for minus pins.