
Operating Method

- Pulling the lever forwards moves the platen upwards and the instrument goes into measurement mode.
 The V-attachment (optional) aids positioning the workpiece on the platen and is useful when measuring a large number of the same size of workpiece.



Bore Gage Stand SERIES 215

• Optimal for efficient measurement of multiple small holes with a bore gage. (SERIES **526**)



SPECIFICATIONS

Code No.	Measuring table displacement (mm)	Measuring table
215-120-10	38	Anvil (ø60 mm)

DIMENSIONS

