
## **Operating Method**

- Pulling the lever forwards moves the platen upwards and the instrument goes into measurement mode.
  The V-attachment (optional) aids positioning the workpiece on the platen and is useful when measuring a large number of the same size of workpiece.



## **Bore Gage Stand SERIES 215**

• Optimal for efficient measurement of multiple small holes with a bore gage. (SERIĖS **526**)



## **SPECIFICATIONS**

Code No.	Measuring table displacement (mm)	Measuring table
215-120-10	38	Anvil (ø60 mm)

## **DIMENSIONS**

