


Contact points, Stems and Holders Optional Accessories for Dial Test Indicators

Contact point (for Metric Models Only*)

* Except for universal type dial test indicator (513-304-10).



Ø0.5 mm contact point (Steel) **Ø0.7 mm contact point (Steel)**



190547 (L2=11.2 mm)
21CAB109 (L2=15.2 mm)
190549 (L2=17.4 mm)
190654 (L2=18.7 mm)
21CAB111 (L2=33.9 mm)
190656 (L2=41.0 mm)

190548 (L2=11.2 mm)
21CAB110 (L2=15.2 mm)
190550 (L2=17.4 mm)
190653 (L2=18.7 mm)
21CAB112 (L2=33.9 mm)
190655 (L2=41.0 mm)

Ø1 mm contact point (Carbide)



103017 (L2=11.2 mm)
131314 (L2=15.2 mm)
103013 (L2=17.4 mm)
137558 (L2=18.7 mm)
131316 (L2=33.9 mm)
136235 (L2=41.0 mm)

Ø2 mm contact point (Carbide)



103010 (L2=11.2 mm)
103011 (L2=15.2 mm)
103006 (L2=17.4 mm)
137557 (L2=18.7 mm)
131324 (L2=33.9 mm)
136013 (L2=41.0 mm)

Ø2 mm contact point (Ruby)



21CZA209 (L2=11.2 mm)
21CZB068 (L2=15.2 mm)
21CZA201 (L2=17.4 mm)
21CZA210 (L2=18.7 mm)
21CZA211 (L2=41.0 mm)

Ø3 mm contact point (Carbide)



103018 (L2=11.2 mm)
131315 (L2=15.2 mm)
103014 (L2=17.4 mm)
137559 (L2=18.7 mm)
131317 (L2=33.9 mm)
136236 (L2=41.0 mm)

Swivel Clamps

For Ø6 mm stem,
Ø8 mm stem, and
dovetail



902053

For Ø4 mm stem,
Ø8 mm stem, and
dovetail




900321

For 0.157 inch DIA. stem,
0.375 inch DIA. stem,
and dovetail



900322





Universal Holder (dovetail clamp)

- A universal holder is an attachment used to mount a dial test indicator in a machine tool spindle so that it can be used to align the spindle axis with a workpiece feature such as a hole center, or a machine axis with an edge. (See diagram on the right.) It also gives some protection against accidental impacts on the indicator.



21CZA233 (Ø8 mm stem)
21CZA231 (0.25 inch DIA. stem)
21CZA229 (Ø6 mm stem)



Dial Test Indicators

Contact points, Stems and Holders
Optional Accessories for Dial Test Indicators

Spanner



Holding Bars

9x9 mm

953638 (Length: 50 mm)
900209 (Length: 100 mm)

0.25 in x 0.5 in

953639 (Length: 2 in)
900306 (Length: 4 in)

ø8 mm (0.315 inch DIA)

900211 (Length: 115 mm/4.528 in)

Stems with Knurled Clamp Ring

ø4 mm
(0.157 inch DIA.)

21CZB131

ø8 mm

21CZB129

0.375 inch DIA.

21CZB130


Stem DIA. ød	Stem with dovetail (Individual item) Code No.	Nut (Individual item) Code No.	Full set (Stem with dovetail+Nut)
ø4	21CAB106	190322	21CZB131
ø6	21CAB103	190322	21CZB128
ø8	21CAB104	190322	21CZB129
ø0.375 in	21CAB105	190322	21CZB130

Centering Holder

- Allows large diameter cylinders or holes to be centered on a machine tool.




901959 (ø8 mm stem)
901997 (0.25 inch DIA. stem)



Optional Accessories for Pocket Type Dial Test Indicators

Contact point (for Metric Models Only)




**ø0.5 mm contact point
(Steel)**




190547 (L2=11.2 mm)
190549 (L2=17.4 mm)
190656 (L2=41.0 mm)

**ø0.7 mm contact point
(Steel)**




190548 (L2=11.2 mm)
190550 (L2=17.4 mm)
190655 (L2=41.0 mm)

**ø1 mm contact point
(Carbide)**



136756 (L2=8.6 mm)
103017 (L2=11.2 mm)
103013 (L2=17.4 mm)
137746 (L2=33.3 mm)
136235 (L2=41.0 mm)

**ø2 mm contact point
(Carbide)**




136104 (L2=8.6 mm)
103010 (L2=11.2 mm)
103006 (L2=17.4 mm)
129949 (L2=33.3 mm)
136013 (L2=41.0 mm)

**ø2 mm contact point
(Ruby)**



21CZA209 (L2=11.2 mm)
21CZA201 (L2=17.4 mm)
21CZA211 (L2=41.0 mm)

**ø3 mm contact point
(Carbide)**




136758 (L2=8.6 mm)
103018 (L2=11.2 mm)
103014 (L2=17.4 mm)
137747 (L2=33.3 mm)
136236 (L2=41.0 mm)

Universal Holder (screw clamp)

- A universal holder is an attachment used to mount a dial test indicator in a machine tool spindle so that it can be used to align the spindle axis with a workpiece feature such as a hole center, or a machine axis with an edge. (See diagram below.) It also gives some protection against accidental impacts on the indicator.



21CZA234 (ø8 mm stem)
21CZA232 (0.25 inch DIA. stem)
21CZA230 (ø6 mm stem)



Swivel Clamps

For ø6 mm stem,
ø8 mm stem,
and dovetail



902053

For ø4 mm stem
and ø8 mm stem,
and dovetail




900321

For 0.157 inch DIA. stem
and 0.375 inch DIA. stem,
and dovetail



900322



Spanner



301336

Holding Bars



9x9 mm

900209 (Length: 100 mm)



ø8 mm (0.315 inch DIA.)

900211 (Length: 115 mm)



0.25x0.5 in

953639 (Length: 2 in)

900306 (Length: 4 in)

Note: Suitable for height gages with a scriber section of 12.7x6.35 mm.

Stems

ø4 mm
(0.157 inch DIA.)

ø8 mm
(0.315 inch DIA.)

0.375 inch DIA.



102036



102822



102081